

Hartford Aviation Group, Inc.

Aircraft Engine Leasing
 One Gold Street
 Hartford Connecticut, 06103 USA
 Tel: 860-549-0096 Fax: 860-525-5351
 hartford@hartfordaviation.com

Revised: 30-Sep-2016

JT9D-7R4D ESN 709605 in Full QEC & BG800 Configuration

TIME SINCE NEW:	7,844	CYCLES SINCE NEW:	4,125
TIME SINCE REPAIR:	4,691	CYCLES SINCE REPAIR:	2,405
TS FAN BLADE CHANGE:	1,944	CS FAN BLADE CHANGE:	1,593

DISK POSTION	PART NUMBER	SERIAL NUMBER	TOTAL TIME	TOTAL CYCLES	CYCLE LIMIT	CYCLE REMAIN	HOUR LIMIT	HOURS REMAIN
FAN ROTOR								
Frt Comp. Rtr Hub	5001331-01	M50729	14,315	3,629	20,000	16,371	N/A	N/A
LOW COMPRESSOR								
	807512	A16610	25,628	9,904	TSO:	5,436	CSO:	2,586
C-1.5	715515	M05388	25,628	9,904	20,000	10,096	N/A	N/A
C-2	760102	M50449	25,628	9,904	20,000	10,096	N/A	N/A
Frt Comp. RR Hub	772403	M39045	25,628	9,904	20,000	10,096	N/A	N/A
C-4	756704	M50745	25,628	9,904	20,000	10,096	N/A	N/A
Coupling, Turbine Shaft	793462	J67034	7,844	4,125	30,000	25,875	N/A	N/A
HIGH COMPRESSOR								
	835715	B09605	7,844	4,125	TSO:	4,691	CSO:	2,405
C-5	669605	J39609	7,844	4,125	20,000	15,875	N/A	N/A
C-6	5002906-01	L21078	7,844	4,125	20,000	15,875	N/A	N/A
C-7	5001607-01	L12975	7,844	4,125	20,000	15,875	N/A	N/A
C-8	5001108-01	L16759	7,844	4,125	20,000	15,875	N/A	N/A
C-9	5001109-01	L20372	7,844	4,125	20,000	15,875	N/A	N/A
C-10	5002410-01	L21776	7,844	4,125	20,000	15,875	N/A	N/A
C-11	5005211-01	L01418	7,844	4,125	20,000	15,875	N/A	N/A
C-12	705922	L16879	7,844	4,125	20,000	15,875	N/A	N/A
C-13	5002413-01	L17070	7,844	4,125	20,000	15,875	N/A	N/A
C-14 *	790014	K92692	7,844	4,125	20,000	15,875	N/A	N/A
C-15 *	5000815-01	K41705	7,844	4,125	20,000	15,875	N/A	N/A
Rear Shaft	808071	AENCAJ7998	5,436	2,586	20,000	17,414	N/A	N/A
HIGH TURBINE								
	812808	C09605	7,844	4,125	TSR:	4,691	CSR:	2,405
T-01 Disk	839501	K88070	7,844	4,125	20,000	15,875	N/A	N/A
T-02 Disk	5001802-01	K99268	7,844	4,125	20,000	15,875	N/A	N/A
1st Airseal (Outer)	735907	JF3051	7,844	4,125	20,000	15,875	N/A	N/A
1st Airseal (Inner)	800326	AKLBE23151	5,436	2,586	20,000	17,414	N/A	N/A
Second Airseal	803674	AKLBG36689	4,691	2,405	20,000	17,595	N/A	N/A
LOW TURBINE								
	5006709-021	D09605	7,844	4,125	TSR:	5,436	CSR:	2,586
T-3	787903	K88134	7,844	4,125	20,000	15,875	N/A	N/A
T-4	787904	L20934	7,844	4,125	20,000	15,875	N/A	N/A
T-5	787905	L20395	7,844	4,125	20,000	15,875	N/A	N/A
T-6	787906	K88412	7,844	4,125	20,000	15,875	N/A	N/A
T3 Airseal	786759	MA7335	7,844	4,125	20,000	15,875	N/A	N/A
T4 Airseal	786760	LV4400	7,844	4,125	20,000	15,875	N/A	N/A
T5 Airseal	798281	ALDLA229466	5,436	2,586	20,000	17,414	N/A	N/A
T6 Airseal	786762	MF5342	7,844	4,125	20,000	15,875	N/A	N/A
Rear Turbine Hub	788018	L01601	7,844	4,125	30,000	25,875	N/A	N/A
Turbine Shaft	5004697-01	L19297	7,844	4,125	30,000	25,875	N/A	N/A

ESN 709605

DESCRIPTION	PART NUMBER	SERIAL NUMBER	TOTAL TIME	TOTAL CYCLES	TSO	CSO	TSI	CSI
Inner Combustion Liner	792698	MB0211	7,844	4,125	4,691	2,405		
Outer Combustion Liner	800089	MH7315	8,805	3,865	4,691	2,405		
Diffuser Case	789996-006	NB0023	32,530	11,202	4,691	2,405		
TEC Case	5005814-035	LV4217	7,844	4,125	5,436	2,586		
T-1 NGV	810571	Qty 65	5,436	2,586	4,691	2,405		
		Qty 1 NEW	4,691	2,405				
T-2 NGV	780992	Qty 84	7,844	4,125	-	-		
		Qty 6 NEW	4,691	2,405				
T-1 Blade Qty 116	800531	VARIOUS	5,436	2,586	-	-		
T-2 Blade Qty 138	808302	VARIOUS	5,436	2,586	-	-		
Fuel Nozzles	801405	Qty 17	unk	unk	4,691	2,405		
		Qty 1 NEW	4,691	2,405				
	801399	Qty 1	unk	unk	4,691	2,405		
		Qty 1 NEW	4,691	2,405				
C 5 -C15 Blades	VARIOUS	NEW	4,691	2,405				
TOBI Duct	815392	AJNBAL1309	5,436	2,586				

MPA Run Performed "1.944" Hours Ago:

EGT Margin = 10 deg. C

* CYCLES REMAINING BEFORE AD 98-21-22R1 DUE:

C14 Disk = 1,595

C15 Disk = 1,595